



*The Leader in  
Animal Comfort*

To learn more visit [Promatinc.com](http://Promatinc.com) or contact us at [sales@promatinc.com](mailto:sales@promatinc.com)  
519.456.2284 | Toll free 1.888.337.6265  [facebook.com/promatinc](https://facebook.com/promatinc)  [@Promat\\_inc](https://twitter.com/Promat_inc)

Founded in 1994, Wilson Agri, based in Northern Ireland, specialize in the happiness of cows.  
Wilson's provide professional barn design services as well as supplying everything for the  
internals of the dairy barn to ensure that the cow has a clean dry comfortable environment.



DEALER INFORMATION:



## COMFORTABLE CLEAN COWS



BROUGHT TO YOU BY




*The Leader in  
Animal Comfort*

# IT'S MORE THAN A STALL...IT'S A COWCOON.

Promat is pleased to introduce COWCOON, the hybrid cow stall produced by Wilson Agri in Northern Ireland that combine the benefits of both comfort and control to provide the ultimate cow stall system.

- Flexible polyethylene tube across bottom portion of loop acts as shock absorber
- Reduces stress on the cow while ensuring proper positioning
- Reduced load on front mountings



*Available in post mounting and custom mounting systems*



*Flexible barriers reduce stress & increase comfort*




*More forgiving than an all steel partition*




*Ensures proper positioning of cow within stall*

## Reduced Lesions on the Spine

Increasing the time cows spend in contact with the stall division often results in spinal lesions, affecting the locomotion of the cow and eventually impacting upon lameness.




**BEFORE:** Increasing lying times often results in spinal lesions




**AFTER:** Healthy cows with no spinal lesions

## Improved Cleanliness

The unique open fronted cowcoon design with its flexible tube ensures that cows rest straighter and not under the stall divisions, ensuring an injury free rest period, with cows unable to defecate or urinate on the beds, resulting in clean cows.



**BEFORE:** Dirty beds result of poor positioning



**AFTER:** Increased resting periods and cleaner cows